PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE.

No. 31. RET. 51 3: 29/01 81 31 31 0 Date: 05/12/2019

It is certified that an inspection team headed by <u>Dr. Sangita Meshram, Medical Officer</u>(Name of Officers with designation) from <u>PHC Tadali, Dist.Chandrapur</u> (Name of Department/Office) inspected Shree Maharishi Vidya Mandir , Mouza Datala , Datala Road, Chandrapur (Name & Address of the School) on <u>27/11/2019</u> .

The water sample was collected from Well (RO) on 27/11/2019 from Shree Maharishi Vidya Mandir and tested at District Laboratory Chandrapur and found Safe for drinking on 30/11/2019 according to Testing Report No - 7373/27-11-2019. With reference to this report it is found that the Shree Maharishi Vidya Mandir (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

It is duely Certified.

Signature with Seat imary Health Centre, Tade!

Name : Dr. Sangita Meshram

Designation: Medical Officer

To

Shree Maharishi Vidya Mandir

Mouza Datala, Datala Road, Chandarpur.

(Name & Address of the Institution)