

Annexure D

BUILDING SAFETY CERTIFICATE

No. 2628

Dated: 05-06-2026

It is certified that the existing building Shree Mahanishi Vidya (name of the building or premises) at Mouja Datala, Datala road, Dist-Chandrapur (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	4	4	4		—	—

The building is owned/occupied by Shree Mahanishi Vidya Mandir (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. (Name of Department/ Govt.) on 01-06-2026 (date of inspection) in the presence of Mrs. Nisha Mehta, Datala road, Chandrapur (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 05-06-2026 for a period of three years in accordance with rule and subject to compliance of the specific conditions as appended.

1. —
2. —
3. —
4. —

Issued on 05-06-2026 at 2:00 pm. by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : Mr. Sunil Rathod

Designation : Sub-Divisional Engineer

Name & Address of Department/ Office: P.W.D. No.1

Chandrapur

Sub Divisional Engineer
Public Works Subdivision No.1
Chandrapur.